

END MILL (Standard Helix) SPEED & FEED RECOMMENDATIONS

| MATERIAL | SPEED [SFM] | END MILL DIAMETER/FEED PER TOOTH [inches] | | | | |
|---------------------------------|----------------|---|-------|------|-------|------|
| | | 1/8" | 1/4" | 1/2" | 3/4" | 1" |
| Aluminum/Aluminum Alloys | 900-1500 | .0005 | .002 | .004 | .005 | .008 |
| Brass/Bronze | 400-750 | .001 | .002 | .003 | .004 | .005 |
| Copper/Copper Alloys | 450-850 | .001 | .002 | .002 | .004 | .006 |
| Cast Iron (Soft) | 300-750 | .001 | .002 | .003 | .006 | .008 |
| Cast Iron (Hard) | 125-350 | .0004 | .0008 | .002 | .003 | .004 |
| Ductile Iron | 150-450 | .0005 | .001 | .002 | .004 | .006 |
| Malleable Iron | 300-550 | .0005 | .001 | .003 | .005 | .007 |
| | | | | | | 1 |
| Magnesium/Magnesium Alloys | 1100-1600 | .001 | .002 | .004 | .006 | .010 |
| Monel/High Nickel Steel | 225-350 | .0005 | .001 | .002 | .003 | .004 |
| Nickel Base Hi-Temp. Alloys | 50-125 | .0004 | .0008 | .001 | .001 | .002 |
| Plastics | 900-1800 | .0015 | .003 | .006 | .010 | .015 |
| Plastics Plastics, Glass Filled | 400-1000 | .0015 | .003 | .006 | .010 | .013 |
| Refactory Alloys | 50-125 | .0015 | .003 | .004 | .000 | .012 |
| Relactory Alloys | 30-123 | .0003 | .001 | .001 | .0013 | .002 |
| Steel (Low Carbon) | 300-600 | .0005 | .001 | .003 | .005 | .007 |
| Steel (Medium Carbon) | 150-450 | .0006 | .0015 | .002 | .004 | .005 |
| Steel (Hardened) | 50-225 | .0002 | .0005 | .001 | .002 | .003 |
| Stainless Steel (Soft) | 250-500 | .0005 | .001 | .002 | .004 | 006 |
| Stainless Steel (Hard) | 75-275 | .0002 | .0005 | .001 | .003 | .005 |
| | | | | | | |
| Titanium (Soft) | 175-400 | .0005 | .001 | .002 | .004 | .006 |
| Titanium (Hard) | 75-250 | .0003 | .0005 | .001 | .002 | .004 |
| FORMULAS | | | | | | |
| FORIVIOLAS | | | | | | |

Cutting Speed: SFM: Dia. x .26 x RPM Feed Per Tooth: IPM: IPT x # of Teeth x RPM

Spindle Speed: RPM: SFM x 3.82 / Tool Dia. Table Feed: IPT: IPM / # of Teeth / RPM

Note: The speed and feed rates shown are suggested starting parameter only and may be increased or decreased depending on factors such as material hardness, equipment and other cutting conditions.